

MODEL B AIR COMPRESSOR PANEL

ITEM	APPROXIMATE SWITCH TRANSFER PRESSURE (oz/in ²)	
	INCREASING PRESSURE	DECREASING PRESSURE
HORN PRESSURE SWITCH NO.1	19	11
COMPRESSOR PRESSURE SWITCH NO.2	33	25

NOTE:
(1) DISCONNECT PANEL POWER BEFORE SERVICING.
(NOTE: RELAY WILL TRANSFER WITH LOSS OF POWER TO PANEL).
(2) PRESSURE SWITCH AND RELAY CONTACTS SHOWN IN UNPRESSURIZED POSITION. SEE BULLETIN 708 FOR ADJUSTMENT.
(3) WITH SILENCE SWITCH IN NORMAL POSITION, HORN WILL SOUND AND RELAY WILL TRANSFER FOR PRESSURES LESS THAN 11 TO 19 oz/in².
(4) WITH SILENCE SWITCH IN SILENCE POSITION, HORN WILL SOUND AND RELAY WILL TRANSFER FOR PRESSURES GREATER THAN 11 TO 19 oz/in².
(5) ELECTRICAL REQUIREMENTS: 120VAC, 60Hz, 1.5 AMP.
(6) RELAY MAX. SWITCHING LOAD: 7.5A/ 1/6 HP @ 120VAC, 7.5A @ 30VDC.

WIRING DIAGRAM

SCHEMATIC

EX-5000 THE RELIABLE AUTOMATIC SPRINKLER CO., INC.
MOUNT VERNON, N.Y.

Accepted for Use
City of New York
Department of Buildings
MEA 256-93-E



WARNING!
THIS FIRE ALARM AND/OR SPRINKLER
EQUIPMENT IS ELECTRONICALLY CONNECTED TO
ELECTRONIX SYSTEMS
CENTRAL STATION ALARMS, INC.
1555 New York Avenue
Huntington Station, NY 11746
Office Central Station
(888) 95-ALARM (800) 698-8811
AND THE **423-2635**
BOTH OFFICES MUST BE NOTIFIED BEFORE WORKING
OR TESTING THIS SYSTEM. THE BUILDING MANAGER
OR SUPERINTENDENT MUST ALSO BE NOTIFIED TO
FULFILL ANY ADDITIONAL REQUIREMENTS.
Failure to comply with above could result in a false alarm.

We're Associates
6-8 Corp. Ctr. Drive
Melville, NY 11747

On-site Contact:
Willie D'Ambrosio 516-816-8355

NO.	DATE	RESULT	INSP. NAME	NO.	DATE	RESULT	INSP. NAME
1	4/17	S	Chlorinated 20001549	13			
2	12/12	S	Chlorinated 20001549	14			
3	2/18	S	Chlorinated 20001549	15			
4	6/18	S	Chlorinated 20001549	16			
5	9/18	S	Chlorinated 20001549	17			
6	12/18	S	Chlorinated 20001549	18			
7	3/19	S	Chlorinated 20001549	19			
8	6/19	S	Chlorinated 20001549	20			
9	9/19	S	Chlorinated 20001549	21			
10	12/19	S	Chlorinated 20001549	22			
11				23			
12				24			

WARNING: This card is for inspection by the Fire Dept.
Do Not deface or remove from premises.

RESULT: S - Satisfactory U - Unsatisfactory (see comments on back)

NOTE: See back of card for Main Drain Results
and Inspector's remarks

FIRE SPRINKLER ASSOCIATES, INC.
41 Mercedes Way, Suite 31
Edgewood, NY 11717
(631) 254-2800